



# CONSTRUCTION EQUIPMENT

280258 VOLVO A35C 4656 - DROP BOX



**Sample No:** VCP299421

**Oil Type:** NOT GIVEN

**Job No:** 280258



## SAMPLE INFORMATION

Sample Number	VCP299421	---	---	---
Sample Date	31 Mar 2021	---	---	---
Machine Hours	12399	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---



## OIL CONDITION

Visc @ 40°C	cSt	141	---	---	---
-------------	-----	-----	-----	-----	-----



## CONTAMINATION

Silicon	ppm	42	---	---	---
Sodium	ppm	3	---	---	---
Potassium	ppm	4	---	---	---



## WEAR METALS

Iron	ppm	173	---	---	---
Copper	ppm	4	---	---	---
Lead	ppm	<1	---	---	---
Tin	ppm	<1	---	---	---
Aluminum	ppm	15	---	---	---
Chromium	ppm	2	---	---	---
Molybdenum	ppm	<1	---	---	---
Nickel	ppm	<1	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	<1	---	---	---
Manganese	ppm	2	---	---	---
Vanadium	ppm	0	---	---	---



## ADDITIVES

Calcium	ppm	50	---	---	---
Magnesium	ppm	4	---	---	---
Zinc	ppm	31	---	---	---
Phosphorus	ppm	348	---	---	---
Barium	ppm	<1	---	---	---
Boron	ppm	18	---	---	---



### STRONGCO EQUIPMENT INC (STE- FOY)

175, rue de Rotterdam  
St-Augustin-de-Desmaures, QC  
CA G3A 2K2  
Contact: Michel Lepage  
mlepage@strongco.com  
T: (418)870-1700  
F: (418)870-1701

### Diagnosis

Échantillonner de nouveau l'équipement au prochain intervalle de vidange afin d'en surveiller la condition. Veuillez préciser la marque, le type et la viscosité de l'huile lors de votre prochain échantillon. Les taux d'usure de tous les composants sont normaux. Il n'y a aucun indice de contamination dans le l'huile. L'état de l'huile est acceptable pour la durée de service.

**Depot:** VOLVO0228  
**Unique No:** 5200987  
**Signed:** Kevin Marson  
**Report Date:** 06 Apr 2021



# CONSTRUCTION EQUIPMENT



## GRAPHS

