



CONSTRUCTION EQUIPMENT

297897 VOLVO A35D 72260 - TRANSMISSION



Sample No: VCP297822

Oil Type: NOT GIVEN

Job No: 297897



SAMPLE INFORMATION

Sample Number	VCP297822	---	---	---
Sample Date	07 Sep 2021	---	---	---
Machine Hours	15299	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---



STRONGCO EQUIPMENT INC (STE- FOY)

175, rue de Rotterdam
 St-Augustin-de-Desmaures, QC
 CA G3A 2K2
 Contact: Michel Lepage
 mlepage@strongco.com
 T: (418)870-1700
 F: (418)870-1701



OIL CONDITION

Visc @ 40°C	cSt	61.6	---	---	---
-------------	-----	------	-----	-----	-----



CONTAMINATION

Silicon	ppm	2	---	---	---
Sodium	ppm	<1	---	---	---
Potassium	ppm	<1	---	---	---



WEAR METALS

Iron	ppm	6	---	---	---
Copper	ppm	75	---	---	---
Lead	ppm	3	---	---	---
Tin	ppm	2	---	---	---
Aluminum	ppm	2	---	---	---
Chromium	ppm	0	---	---	---
Molybdenum	ppm	0	---	---	---
Nickel	ppm	<1	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	3	---	---	---
Manganese	ppm	<1	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	1654	---	---	---
Magnesium	ppm	4	---	---	---
Zinc	ppm	513	---	---	---
Phosphorus	ppm	772	---	---	---
Barium	ppm	0	---	---	---
Boron	ppm	17	---	---	---

Diagnosis

Échantillonner de nouveau l'équipement au prochain intervalle de vidange afin d'en surveiller la condition. Veuillez préciser la marque, le type et la viscosité de l'huile lors de votre prochain échantillon. Les taux d'usure de tous les composants sont normaux. Il n'y a aucun indice de contamination dans le le fluide. L'état de le fluide est acceptable pour la durée de service.

Depot: VOLVO0228
Unique No: 5279574
Signed: Kevin Marson
Report Date: 15 Sep 2021



CONSTRUCTION EQUIPMENT



GRAPHS

