



CONSTRUCTION EQUIPMENT

313560 VOLVO A25G 752104 - REAR AXLE



Sample No: VCP334315
Oil Type: VOLVO API GL-5 SAE 75W90
Job No: 313560



SAMPLE INFORMATION

Sample Number	VCP334315	---	---	---
Sample Date	03 Feb 2022	---	---	---
Machine Hours	1271	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

STRONGCO EQUIPMENT INC (STE- FOY)

175, rue de Rotterdam
 St-Augustin-de-Desmaures, QC
 CA G3A 2K2
 Contact: Michel Lepage
 mlepage@strongco.com
 T: (418)870-1700
 F: (418)870-1701



OIL CONDITION

Visc @ 40°C	cSt	█ 137	---	---	---
-------------	-----	-------	-----	-----	-----



CONTAMINATION

Silicon	ppm	█ 3	---	---	---
Sodium	ppm	█ <1	---	---	---
Potassium	ppm	█ <1	---	---	---



WEAR METALS

Iron	ppm	█ 111	---	---	---
Copper	ppm	█ 5	---	---	---
Lead	ppm	█ <1	---	---	---
Tin	ppm	█ <1	---	---	---
Aluminum	ppm	█ <1	---	---	---
Chromium	ppm	█ 2	---	---	---
Molybdenum	ppm	█ 2	---	---	---
Nickel	ppm	█ <1	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ 4	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	39	---	---	---
Magnesium	ppm	█ 0	---	---	---
Zinc	ppm	█ 16	---	---	---
Phosphorus	ppm	1061	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	179	---	---	---

Diagnosis

Échantillonner de nouveau l'équipement au prochain intervalle de vidange afin d'en surveiller la condition. Les taux d'usure de tous les composants sont normaux. Il n'y a aucun indice de contamination dans le l'huile. L'état de l'huile est acceptable pour la durée de service.

Depot: VOLVO0228
Unique No: 5356111
Signed: Wes Davis
Report Date: 09 Feb 2022



CONSTRUCTION EQUIPMENT



GRAPHS

