

CONSTRUCTION EQUIPMENT VOLVO L90H 623168 - TRANSMISSION (AUTO)



Sample No: VCP332701

VOLVO AUTOMATIC TRANSMISSION FLUID AT102

Oil Type: Job No:

VOLVO					
	E INFORMATION				 Attended to the
Sample Number		VCP332701			
Sample Date		20 May 2022			
Machine Hours		4834			 6 - 38403 BURNT LAKE
Oil Hours		2000			 RED DEER COUNTY, AB CA T4S 2L4
Oil Changed		Changed NORMAL			 CA 143 2L4 Contact: Perry Doyle
Sample Status		NORMAL			 pdoyle@strongco.com
VOLVO					T: (403)346-3473
V OIL CON	IDITION				F: (403)346-3487
Visc @ 40°C	cSt	30.4			 1. (405)540 5407
TONTAN	MINATION				Diagnosis
		<u>.</u>	<u>_</u>	<u>.</u>	 Resample at the next s
Silicon	ppm	1 0			 to monitor.All compon
Sodium	ppm	0			 are normal. There is no
Potassium	ppm	5			 any contamination in t
VOLVO					condition of the fluid is for the time in service.
WEAR N	METALS				for the time in service.
Iron	ppm	40			
Copper	ppm	9			
Lead	ppm	■ <1			
Tin	ppm	 <1			
Aluminum	ppm	1			
Chromium	ppm				
Molybdenum	ppm				
Nickel	ppm				
Titanium	ppm	0			
Silver	ppm	0			
Manganese	ppm	3			
Vanadium	ppm	0			
	VES				
Calcium	ppm	82			
Magnesium	ppm	5			
Zinc	ppm	40			
Phosphorus	ppm	201			
Barium	ppm	1			
Boron	ppm	64			



RAIL

vice interval nt wear rates ndication of fluid. The acceptable

Depot:	VOLVO9652		
Unique No:	5408106		
Signed:	Wes Davis		
Report Date:	27 May 2022		

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO

