

# CONSTRUCTION EQUIPMENT 8000362284 VOLVO L 150H 6743 - FRONT AXLE



Sample No: VCP391972
Oil Type: NOT GIVEN
Job No: 8000362284

VOLVO				
SAMPLE	INFORMATION			
Sample Number	-	VCP391972	 	
Sample Date		27 Apr 2023	 	
Machine Hours		4183	 	
Oil Hours		0	 	
Oil Changed		N/A	 	
Sample Status		NORMAL	 	
VOLVO				
OIL COND	ITION			
Visc @ 40°C	cSt	44.8	 	
VOLVO	INIATION			
CONTAM	INATIUN			
Water	%	NEG	 	
Silicon	ppm	<b>■8</b>	 	
Sodium	ppm	■4	 	
Potassium	ppm	<b>1</b>	 	
WEAR M	ETALS			
Iron	ppm	<b>46</b>	 	
Copper	ppm	<b>■</b> 9	 	
Lead	ppm	<b>■&lt;1</b>	 	
Tin	ppm	<b>■</b> 0	 	
Aluminum	ppm	<b>■&lt;1</b>	 	
Chromium	ppm	<b>1</b>	 	
Molybdenum	ppm	1	 	
Nickel	ppm	<b>■&lt;1</b>	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm	2	 	
Vanadium	ppm	0	 	
ADDITIV	ES			
Calcium	ppm	3722	 	
Magnesium	ppm	9	 	
Zinc	ppm	1470	 	
Phosphorus	ppm	1548	 	
Barium	ppm	0	 	
Boron	ppm	126	 	
23.311	PPIII			



### STRONGCO EQUIP (AB)

6 - 38403 BURNT LAKE TRAIL RED DEER COUNTY, AB CA T4S 2L4 Contact: Perry Doyle pdoyle@strongco.com T: (403)346-3473 F: (403)346-3487

## Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO9652Unique No:5567783Signed:Kevin MarsonReport Date:03 May 2023



# **CONSTRUCTION EQUIPMENT**





#### GRAPHS

