



# CONSTRUCTION EQUIPMENT

## VOLVO L110F VCEL110FE00061705 - TRANSMISSION (AUTO)



**Sample No:** VCP381713

**Oil Type:** DEXRON III

**Job No:**



### SAMPLE INFORMATION

Sample Number	VCP381713	---	---	---
Sample Date	16 May 2023	---	---	---
Machine Hours	20100	---	---	---
Oil Hours	0	---	---	---
Oil Changed	N/A	---	---	---
Sample Status	NORMAL	---	---	---



### TRANSPORT CG BILODEAU INC

50 RUE PIVOINES  
 METABETCHAOUAN, QC  
 CA G8G 1K8  
 Contact: Gratien Biladeau  
 gsbill@hotmail.com  
 T: (418)349-8845  
 F:



### OIL CONDITION

Visc @ 40°C	cSt	█ 25.9	---	---	---
-------------	-----	--------	-----	-----	-----



### CONTAMINATION

Silicon	ppm	█ 6	---	---	---
Sodium	ppm	█ 4	---	---	---
Potassium	ppm	█ <1	---	---	---



### WEAR METALS

Iron	ppm	█ 21	---	---	---
Copper	ppm	█ 4	---	---	---
Lead	ppm	█ <1	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ 4	---	---	---
Chromium	ppm	█ 0	---	---	---
Molybdenum	ppm	█ 0	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	█ 0	---	---	---
Manganese	ppm	█ <1	---	---	---
Vanadium	ppm	0	---	---	---



### ADDITIVES

Calcium	ppm	█ 99	---	---	---
Magnesium	ppm	█ <1	---	---	---
Zinc	ppm	█ 16	---	---	---
Phosphorus	ppm	█ 217	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 71	---	---	---

### Diagnosis

Échantillonner de nouveau l'équipement au prochain intervalle de vidange afin d'en surveiller la condition. Le fluide n'était pas spécifié, toutefois, une comparaison avec d'autres fluides indiqua que ce fluide est du (GENERIC) DEXRON III. Veuillez confirmer. Les taux d'usure de tous les composants sont normaux. Il n'y a aucun indice de contamination dans le fluide. L'état de le fluide est acceptable pour la durée de service.

**Depot:** TRA50MET  
**Unique No:** 5579163  
**Signed:** Wes Davis  
**Report Date:** 17 May 2023



# CONSTRUCTION EQUIPMENT



## GRAPHS

