



CONSTRUCTION EQUIPMENT

36772 VOLVO L180H 5567 - TRANSMISSION (AUTO)



Sample No: VCP353157
Oil Type: VOLVO AT 102
Job No: 36772



SAMPLE INFORMATION

Sample Number	VCP353157	---	---	---
Sample Date	07 Jun 2023	---	---	---
Machine Hours	2139	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---

STRONGCO EQUIPMENT

5200 BOUL ST JOSEPH
TROIS RIVIERE, QC
CA G8Z 4L8
Contact: Sebastien Rocheleau
srocheleau@strongco.com
T: (855)840-0828
F: (819)840-0829



OIL CONDITION

Visc @ 40°C	cSt	█ 29.3	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Silicon	ppm	█ 2	---	---	---
Sodium	ppm	█ <1	---	---	---
Potassium	ppm	█ <1	---	---	---



WEAR METALS

Iron	ppm	█ <1	---	---	---
Copper	ppm	█ <1	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ 0	---	---	---
Chromium	ppm	█ 0	---	---	---
Molybdenum	ppm	█ <1	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	█ 0	---	---	---
Silver	ppm	█ 0	---	---	---
Manganese	ppm	█ 0	---	---	---
Vanadium	ppm	█ 0	---	---	---



ADDITIVES

Calcium	ppm	█ 69	---	---	---
Magnesium	ppm	█ 1	---	---	---
Zinc	ppm	█ 3	---	---	---
Phosphorus	ppm	█ 203	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 87	---	---	---

Diagnosis

Échantillonner de nouveau l'équipement au prochain intervalle de vidange afin d'en surveiller la condition. Les taux d'usure de tous les composants sont normaux. Il n'y a aucun indice de contamination dans le fluide. L'état de le fluide est acceptable pour la durée de service.

Depot: STR520TRO
Unique No: 5602997
Signed: Wes Davis
Report Date: 22 Jun 2023



CONSTRUCTION EQUIPMENT



VOLVO GRAPHS

