

Sample No: VCP392240
Oil Type: VOLVO WB 102

**Job No:** 369835

-	



## **Strongco Equipment**

5179 Fountain St N.
Breslau, ON
CA NOB 1M0
Contact: Nick Sanders
nsanders@strongco.com
T: (519)744-3518
F: (519)744-3284

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. The water content is negligible. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot:CASKITUnique No:5604014Signed:Kevin MarsonReport Date:29 Jun 2023



## **CONSTRUCTION EQUIPMENT**





