



CONSTRUCTION EQUIPMENT

8-370246 VOLVO L180H 5658 - TRANSMISSION (AUTO)



Sample No: VCP394582
Oil Type: DEXRON III
Job No: 8-370246



SAMPLE INFORMATION

Sample Number	VCP394582	---	---	---
Sample Date	28 Jun 2023	---	---	---
Machine Hours	549	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---

STRONGCO EQUIPMENT INC.

1640 ENTERPRISE ROAD
MISSISSAUGA, ON
CA L4W 4L4

Contact: Jason Roth
JRoth2@strongco.com
T: (905)670-5100
F: (905)670-2338



OIL CONDITION

Visc @ 40°C	cSt	█ 27.9	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Silicon	ppm	█ 7	---	---	---
Sodium	ppm	█ 3	---	---	---
Potassium	ppm	█ 2	---	---	---



WEAR METALS

Iron	ppm	█ 31	---	---	---
Copper	ppm	█ 4	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ <1	---	---	---
Chromium	ppm	█ <1	---	---	---
Molybdenum	ppm	█ <1	---	---	---
Nickel	ppm	█ <1	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	3	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	█ 81	---	---	---
Magnesium	ppm	█ 2	---	---	---
Zinc	ppm	█ 16	---	---	---
Phosphorus	ppm	█ 205	---	---	---
Barium	ppm	█ 4	---	---	---
Boron	ppm	█ 76	---	---	---

Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) DEXRON III. Please confirm. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot: SHEMIS
Unique No: 5605893
Signed: Kevin Marson
Report Date: 10 Jul 2023



CONSTRUCTION EQUIPMENT



GRAPHS

