

## **CONSTRUCTION EQUIPMENT** 31694 - TRANSMISSION (AUTO)



- TRA

## Sample No: VCP428252

**Oil Type:** VOLVO AUTOMATIC TRANSMISSION FLUID AT102

## Job No:

	E INFORMATION	I _		
Sample Number		VCP428252	 	
Sample Date		16 Jul 2023	 	 GREAT WEST EQUIPMENT
Machine Hours		9524	 	 1600 KOSMINA ROAD, 123 L&A CROSS RD
Oil Hours		0	 	 VERNON, BC
Oil Changed		N/A	 	 CA V1T 8T2
Sample Status		NORMAL	 	 Contact: Garry Beach
				gbeach@gwequipment.com
	DITION			T: (250)549-4232
Visc @ 40°C	cSt	25.6	 	 F: (250)549-3397
VISC @ 40 C	CSL	25.0	 	
VOLVO				 Diagnosis
CONTA	MINATION			Confirm the source of the lubricant
Silicon	ppm	5	 	 being utilized for top-up/fill.
Sodium	ppm	4	 	 Resample at the next service interval
Potassium	ppm	2	 	 to monitor.All component wear rates
		_		are normal. There is no indication of
WEAR I	METALS			any contamination in the fluid. Additive levels indicate the addition
Iron	ppm	90	 	 of a different brand, or type of fluid.
Copper	ppm	<b>1</b> 4	 	 The condition of the fluid is
Lead	ppm	<1	 	 acceptable for the time in service.
Tin	ppm	0	 	
Aluminum	ppm	13	 	
Chromium	ppm		 	
Molybdenum	ppm	_ <b>_</b> <1	 	
Nickel	ppm	0	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	2	 	
Vanadium	ppm	0	 	
ADDITI	VES			
Calcium	ppm	42	 	
Magnesium	ppm	2	 	
Zinc	ppm	17	 	
Phosphorus	ppm	183	 	
Barium	ppm	□ <1	 	
Boron	ppm	58	 	

Depot:	MARVER		
Unique No:	5607470		
Signed:	Wes Davis		
Report Date:	17 Jul 2023		


Contact/Location: Garry Beach - MARVER

## **CONSTRUCTION EQUIPMENT**



GRAPHS

VOLVO



Report Id: MARVER [WCAMIS] 02570424 (Generated: 07/17/2023 14:40:28) Rev: 1