CONSTRUCTION EQUIPMENT VOLVO EC350EL 314290 - HYDRAULIC SYSTEM 372291

Sample No:	VCP353041
Oil Type:	VOLVO SUPER HYDRAULIC OIL 46
Job No:	372291

VOLVO

SAMPLE INFORMATION Sample Number VCP353041 Sample Date 19 Jul 2023 Machine Hours 2621 Oil Hours 2621 Oil Changed Not Changd ABNORMAL Sample Status **OIL CONDITION** Visc @ 40°C cSt **A** 35.8 CONTAMINATION Particles >4µm 1997 548 Particles >6µm Particles >14µm 44

ISO 4406:1999 (c)		18/16/13	 	
Silicon	ppm	4	 	
Sodium	ppm	∎1	 	
Potassium	ppm	□ <1	 	

VOLVO	AFTALC			
WLAK I	METALS			
Iron	ppm	5	 	
Copper	ppm	1 3	 	
Lead	ppm	■ <1	 	
Tin	ppm	□ <1	 	
Aluminum	ppm	□<1	 	
Chromium	ppm	1	 	
Molybdenum	ppm	 <1	 	
Nickel	ppm	■ <1	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	0	 	
Vanadium	ppm	0	 	

ADDITIVES					
Calcium	ppm	119			
Magnesium	ppm	6			
Zinc	ppm	484			
Phosphorus	ppm	412			
Barium	ppm	 <1			
Boron	ppm	 <1			



STRONGCO EQUIP (AB)

6 - 38403 BURNT LAKE TRAIL **RED DEER COUNTY, AB** CA T4S 2L4 Contact: Joseph St Peter jstpeter@strongco.com T: (403)346-3473 F: (403)346-3487

Diagnosis

Confirm the source of the lubricant being utilized for top-up/fill. Resample at the next service interval to monitor. The fluid was specified as VOLVO SUPER HYDRAULIC OIL 46, however, a fluid match indicates that this fluid is ISO 32 AW Hydraulic Oil. Please confirm the oil type and grade on your next sample.All component wear rates are normal. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable. Viscosity of sample indicates oil is within ISO 32 range, advise investigate. This plus the additive levels indicates that this is not the same brand, or type of oil as reported. The condition of the oil is acceptable for the time in service.

Depot: VOLVO9652 Unique No: 5616537 Signed: Kevin Marson Report Date: 24 Jul 2023

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO

