Sample No: VCP394977
Oil Type: NOT GIVEN
Job No: 368254

SAMPLE	INFORMATION			
Sample Number	-	VCP394977	 	
Sample Date		12 Jul 2023	 	
Machine Hours		4516	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
OIL CON	DITION			
Visc @ 40°C	cSt	43.8	 	
VOLVO				
	MINATION			
Silicon	ppm	13	 	
Sodium	ppm	■ 9	 	
Potassium	ppm	2	 	
VOLVO				
WEAR N	METALS			
Iron	ppm	9 1	 	
Copper	ppm	5	 	
Lead	ppm	■ 0	 	
Tin	ppm	□ 0	 	
Aluminum	ppm	2	 	
Chromium	ppm	■ 3	 	
Molybdenum	ppm	4	 	
Vickel	ppm	■<1	 	
Titanium	ppm	<1	 	
Silver	ppm	<1	 	
Manganese	ppm	6	 	
Vanadium	ppm	0	 	
VOLVO				
ADDITIV	IES			
Calcium	ppm	3865	 	
Magnesium	ppm	13	 	
Zinc	ppm	1605	 	
Phosphorus	ppm	1405	 	
Barium	ppm	0	 	
Boron	ppm	110	 	

STRONGCO EQUIPMENT (CE)

1051 Heritage Rd.
Burlington, ON
CA L7L 4Y1
Contact: Sue Hooton
shooton@strongco.com
T: (905)331-3835
F: (905)643-6077

Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO0252Unique No:5616571Signed:Wes DavisReport Date:21 Jul 2023



CONSTRUCTION EQUIPMENT





