



# CONSTRUCTION EQUIPMENT

BERGEN 8000372864 VOLVO L60H 622360 - TRANSMISSION (AUTO)



**Sample No:** VCE07567  
**Oil Type:** VOLVO EXTRA AUTOMATIC FLUID  
**Job No:** 8000372864



## SAMPLE INFORMATION

Sample Number	VCE07567	---	---	---
Sample Date	17 Jul 2023	---	---	---
Machine Hours	4633	---	---	---
Oil Hours	500	---	---	---
Oil Changed	Not Changed	---	---	---
Sample Status	NORMAL	---	---	---

## STRONGCO EQUIPMENT

255 BAIG BOULEVARD  
MONCTON, NB  
CA E1E 1E1  
Contact: Kevin Pent  
kpent@strongco.com  
T: (506)857-8425  
F: (506)857-0851



## OIL CONDITION

Visc @ 40°C	cSt	█ 27.8	---	---	---
-------------	-----	--------	-----	-----	-----



## CONTAMINATION

Silicon	ppm	█ 6	---	---	---
Sodium	ppm	█ 3	---	---	---
Potassium	ppm	█ 1	---	---	---



## WEAR METALS

Iron	ppm	█ 41	---	---	---
Copper	ppm	█ 4	---	---	---
Lead	ppm	█ <1	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ 4	---	---	---
Chromium	ppm	█ <1	---	---	---
Molybdenum	ppm	█ <1	---	---	---
Nickel	ppm	█ <1	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	█ 1	---	---	---
Manganese	ppm	█ 2	---	---	---
Vanadium	ppm	0	---	---	---



## ADDITIVES

Calcium	ppm	█ 126	---	---	---
Magnesium	ppm	█ 8	---	---	---
Zinc	ppm	█ 65	---	---	---
Phosphorus	ppm	█ 246	---	---	---
Barium	ppm	█ <1	---	---	---
Boron	ppm	█ 75	---	---	---

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

**Depot:** SHE255MON  
**Unique No:** 5617758  
**Signed:** Kevin Marson  
**Report Date:** 01 Aug 2023



# CONSTRUCTION EQUIPMENT



## GRAPHS

