



# CONSTRUCTION EQUIPMENT

REGION OF PEEL 8-372823 VOLVO L60H 622787 - FRONT AXLE



Sample No: VCP380465

Oil Type: NOT GIVEN

Job No: 8-372823



## SAMPLE INFORMATION

Sample Number	VCP380465	VCP353329	---	---
Sample Date	20 Jul 2023	06 Dec 2022	---	---
Machine Hours	2028	1024	---	---
Oil Hours	0	0	---	---
Oil Changed	Changed	Changed	---	---
Sample Status	NORMAL	NORMAL	---	---



### STRONGCO EQUIPMENT INC.

1640 ENTERPRISE ROAD  
MISSISSAUGA, ON  
CA L4W 4L4

Contact: Janice Cripps  
jcripps@strongco.com  
T: (905)565-3876  
F: (905)670-2338



## OIL CONDITION

Visc @ 40°C	cSt	48.0	43.3	---	---
-------------	-----	------	------	-----	-----



## CONTAMINATION

Silicon	ppm	12	12	---	---
Sodium	ppm	2	9	---	---
Potassium	ppm	<1	2	---	---



## WEAR METALS

Iron	ppm	70	110	---	---
Copper	ppm	<1	1	---	---
Lead	ppm	0	0	---	---
Tin	ppm	0	0	---	---
Aluminum	ppm	1	1	---	---
Chromium	ppm	2	5	---	---
Molybdenum	ppm	1	4	---	---
Nickel	ppm	<1	<1	---	---
Titanium	ppm	0	<1	---	---
Silver	ppm	0	0	---	---
Manganese	ppm	5	12	---	---
Vanadium	ppm	0	0	---	---



## ADDITIVES

Calcium	ppm	4199	4177	---	---
Magnesium	ppm	16	12	---	---
Zinc	ppm	1655	1611	---	---
Phosphorus	ppm	1424	1407	---	---
Barium	ppm	0	0	---	---
Boron	ppm	125	116	---	---

## Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: SHEMIS  
Unique No: 5617798  
Signed: Wes Davis  
Report Date: 27 Jul 2023



# CONSTRUCTION EQUIPMENT



## VOLVO GRAPHS

