



CONSTRUCTION EQUIPMENT

BECAR 374208 VOLVO L110H 631836 - REAR AXLE



Sample No: VCP392220

Oil Type: NOT GIVEN

Job No: 374208



SAMPLE INFORMATION

Sample Number	VCP392220	---	---	---
Sample Date	03 Aug 2023	---	---	---
Machine Hours	12549	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---



STRONGCO INC

1575 RUE BERSIMIS
CHICOUTIMI, QC
CA G7K 1G9

Contact: Dany Levesque
dlevesque@strongco.com
T: (418)690-1724
F: (418)690-5002



OIL CONDITION

Visc @ 40°C	cSt	42.1	---	---	---
-------------	-----	------	-----	-----	-----



CONTAMINATION

Silicon	ppm	17	---	---	---
Sodium	ppm	8	---	---	---
Potassium	ppm	1	---	---	---



WEAR METALS

Iron	ppm	78	---	---	---
Copper	ppm	1	---	---	---
Lead	ppm	0	---	---	---
Tin	ppm	0	---	---	---
Aluminum	ppm	2	---	---	---
Chromium	ppm	<1	---	---	---
Molybdenum	ppm	<1	---	---	---
Nickel	ppm	<1	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	1	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	4432	---	---	---
Magnesium	ppm	19	---	---	---
Zinc	ppm	1681	---	---	---
Phosphorus	ppm	1465	---	---	---
Barium	ppm	<1	---	---	---
Boron	ppm	131	---	---	---

Diagnosis

Échantillonner de nouveau l'équipement au prochain intervalle de vidange afin d'en surveiller la condition. Veuillez préciser la marque, le type et la viscosité de l'huile lors de votre prochain échantillon. Les taux d'usure de tous les composants sont normaux. La teneur en eau est négligeable. Il n'y a aucun indice de contamination dans l'huile. L'état de l'huile est acceptable pour la durée de service.

Depot: VOLVO0230
Unique No: 5619959
Signed: Kevin Marson
Report Date: 10 Aug 2023



CONSTRUCTION EQUIPMENT



GRAPHS

