

CONSTRUCTION EQUIPMENT

TRADE IN 374084 VOLVO EC220EL 310758 - DIESEL ENGINE

Sample No: VCP380124

Oil Type: VOLVO ULTRA DIESEL ENGINE OIL 15W40 VDS-3

Job No: 374084

VOLVO				
SAMPLE	INFORMATIO	N		
Sample Number		VCP380124	 	
Sample Date		08 Aug 2023	 	
Machine Hours		8202	 	
Oil Hours		0	 	
Oil Changed		Not Changd	 	
Sample Status		ABNORMAL	 	
OIL CON	DITION			
Visc @ 100°C	cSt	<u> 11.7</u>	 	
Oxidation (PA)	%	76	 	
LUNTAN	IINATION			
_		·		
Soot %	%	■0	 	
Nitration (PA)	%	79	 	
Sulfation (PA)	%	61	 	
Glycol	%	NEG	 	
Fuel	%	■ 0.7	 	
Silicon	ppm	■8	 	
Sodium	ppm	■13	 	
Potassium	ppm	■<1	 	
WEAR M	IFTAI S			
WLAN	ILIVE2			

VOLVO				
WEAR MI	ETALS			
Iron	ppm	13	 	
Copper	ppm	■ 3	 	
Lead	ppm	-<1	 	
Tin	ppm	-<1	 	
Aluminum	ppm	2	 	
Chromium	ppm	■ <1	 	
Molybdenum	ppm	60	 	
Nickel	ppm	■0	 	
Titanium	ppm	<1	 	
Silver	ppm	■ 0	 	
Manganese	ppm	■<1	 	
Vanadium	ppm	0	 	

ADDITI	VES			
Calcium	ppm	1728	 	
Magnesium	ppm	■377	 	
Zinc	ppm	1242	 	
Phosphorus	ppm	■1085	 	
Barium	ppm	■<1	 	
Boron	ppm	41	 	



STRONGCO EQUIPMENT

54 IBER ROAD
OTTAWA, ON
CA K2S 1E8
Contact: Jason Hiles
jhiles@strongco.com
T:
F: (613)836-2614

Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. Fuel content negligible. There is no indication of any contamination in the oil. Viscosity of sample indicates oil is within SAE 30 range, advise investigate. The condition of the oil is acceptable for the time in service.

Depot:SHESTIUnique No:5620130Signed:Kevin MarsonReport Date:11 Aug 2023



CONSTRUCTION EQUIPMENT





