



CONSTRUCTION EQUIPMENT

371606 VOLVO A40G 342484 - REAR AXLE



Sample No: VCP382319
Oil Type: VOLVO PREMIUM GEAR OIL 80W-90 GL-5
Job No: 371606



SAMPLE INFORMATION

Sample Number	VCP382319	---	---	---
Sample Date	11 Jul 2023	---	---	---
Machine Hours	9448	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---

STRONGCO EQUIPMENT-EDMONTON
 25616 117 Ave NW
 Acheson, AB
 CA T7X 6C2
 Contact: Jonathan Morton
 jmorton@strongco.com
 T: (780)464-1909
 F: (780)464-0434

OIL CONDITION

Visc @ 40°C	cSt	88.0	---	---	---
-------------	-----	------	-----	-----	-----

CONTAMINATION

Silicon	ppm	2	---	---	---
Sodium	ppm	0	---	---	---
Potassium	ppm	<1	---	---	---

WEAR METALS

Iron	ppm	88	---	---	---
Copper	ppm	<1	---	---	---
Lead	ppm	0	---	---	---
Tin	ppm	0	---	---	---
Aluminum	ppm	<1	---	---	---
Chromium	ppm	1	---	---	---
Molybdenum	ppm	<1	---	---	---
Nickel	ppm	<1	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	2	---	---	---
Vanadium	ppm	0	---	---	---

ADDITIVES

Calcium	ppm	15	---	---	---
Magnesium	ppm	1	---	---	---
Zinc	ppm	11	---	---	---
Phosphorus	ppm	471	---	---	---
Barium	ppm	0	---	---	---
Boron	ppm	20	---	---	---

Diagnosis
 Confirm the source of the lubricant being utilized for top-up/fill. Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is acceptable for the time in service.

Depot: VOLVO3908
Unique No: 5620478
Signed: Wes Davis
Report Date: 11 Aug 2023



CONSTRUCTION EQUIPMENT



GRAPHS

