

# CONSTRUCTION EQUIPMENT 374467 VOLVO A40G 353347 - MIDDLE AXLE



Sample No: VCP394843

Oil Type: VOLVO SUPER GEAR OIL 75W-80-GO102

**Job No:** 374467

SAMPLE	INFORMATIO	N			
Sample Number	_	VCP394843			
Sample Date		11 Aug 2023			
Machine Hours		1014			
Oil Hours		1000			
Oil Changed		Not Changd			
Sample Status		NORMAL			
OIL CONDITION					
Visc @ 40°C	cSt	<b>51.1</b>			
Visc @ 40 C	CSt	<b>31.1</b>			
VOLVO					
CONTAM	IINATION				
Silicon	ppm	<b>3</b>			
Sodium	ppm	<b>3</b>			
Potassium	ppm	<b>4</b>			
WEAR METALS					
Iron	ppm	<b>253</b>			
Copper	ppm	<b>2</b>			
Lead	ppm	<b>0</b>			
Tin	ppm	■0			
Aluminum	ppm	<b>-&lt;1</b>			
Chromium	ppm	<b>4</b>			
Molybdenum	ppm	<b>7</b>			
Nickel	ppm	<b>■&lt;1</b>			
Titanium	ppm	0			
Silver	ppm	<1			
Manganese	ppm	<b>9</b>			
Vanadium	ppm	0			
ADDITIV	ES				
Calcium	ppm	20			
Magnesium	ppm	<b>1</b>			
Zinc	ppm	14			
Phosphorus	ppm	2486			
Barium	ppm	<b>■&lt;1</b>			
Boron	ppm	<b>255</b>			



#### **Strongco Equipment**

5179 Fountain St N. Breslau, ON CA N0B 1M0 Contact: Villamor Pingol vpingol@strongco.com T: (519)744-3518 F: (519)744-3284

### Diagnosis

Confirm the source of the lubricant being utilized for top-up/fill. Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is acceptable for the time in service.

Depot: CASKIT
Unique No: 5629966
Signed: Kevin Marson
Report Date: 21 Aug 2023



## **CONSTRUCTION EQUIPMENT**





