

## **CONSTRUCTION EQUIPMENT**

ST MARYS 374470 VOLVO A40G 353338 - MIDDLE AXLE

Sample No: VCP394633

Oil Type: VOLVO SUPER GEAR OIL 75W-80-GO102

**Job No:** 374470

VOLVO					
SAMPLE	INFORMATION				
Sample Number	•	VCP394633			
Sample Date		16 Aug 2023			
Machine Hours		1000			
Oil Hours		1000			
Oil Changed		Not Changd			
Sample Status		NORMAL			
OIL CONDITION					
Visc @ 40°C	cSt	<b>51.0</b>			
CONTAMINATION					
Silicon	ppm	<u>5</u>			
Sodium	ppm	<b>4</b>			
Potassium	ppm	<b>9</b>			
WEAR N	IETALS				
Iron	ppm	■327			
Copper	ppm	<b>■</b> 2			
Lead	ppm	■0			
Tin	ppm	<b>0</b>			
Aluminum	ppm	<b></b>			
Chromium	ppm	<b>■</b> 5			
Molybdenum	ppm	<b>11</b>			
Nickel	ppm	<b>1</b>			
Titanium	ppm	0			
Silver	ppm	0			
Manganese	ppm	<b>10</b>			
Vanadium	ppm	0			
ADDITIV	JES 231				
Calcium	ppm	17			
Magnesium	ppm	<b></b>			
Zinc	ppm	13			
Phosphorus	ppm	2489			
Barium	ppm	<b>□</b> 0			
Boron	ppm	<b>248</b>			



### **Strongco Equipment**

5179 Fountain St N. Breslau, ON CA N0B 1M0 Contact: Villamor Pingol vpingol@strongco.com T: (519)744-3518 F: (519)744-3284

## Diagnosis

Confirm the source of the lubricant being utilized for top-up/fill. Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is acceptable for the time in service.

Depot:CASKITUnique No:5629968Signed:Kevin MarsonReport Date:21 Aug 2023



# **CONSTRUCTION EQUIPMENT**





#### GRAPHS

