



# CONSTRUCTION EQUIPMENT

362117 VOLVO EW220E NOUNITVCE61464 - FRONT AXLE



**Sample No:** VCE61464  
**Oil Type:** SAE 75W90  
**Job No:** 362117



## SAMPLE INFORMATION

Sample Number	VCE61464	---	---	---
Sample Date	15 Aug 2023	---	---	---
Machine Hours	5119	---	---	---
Oil Hours	5119	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---

**CITY OF REGINA - FLEET SERVICES DEPT**  
 2476 VICTORIA AVENUE, BOX 1790  
 REGINA, SK  
 CA S4P 3C8  
 Contact: Curtis Jors  
 cjors@regina.ca  
 T: (306)777-7674  
 F: (306)777-6813



## OIL CONDITION

Visc @ 40°C	cSt	53.0	---	---	---
-------------	-----	------	-----	-----	-----



## CONTAMINATION

Silicon	ppm	10	---	---	---
Sodium	ppm	16	---	---	---
Potassium	ppm	3	---	---	---

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



## WEAR METALS

Iron	ppm	22	---	---	---
Copper	ppm	5	---	---	---
Lead	ppm	0	---	---	---
Tin	ppm	0	---	---	---
Aluminum	ppm	1	---	---	---
Chromium	ppm	1	---	---	---
Molybdenum	ppm	<1	---	---	---
Nickel	ppm	1	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	6	---	---	---
Vanadium	ppm	0	---	---	---



## ADDITIVES

Calcium	ppm	3534	---	---	---
Magnesium	ppm	11	---	---	---
Zinc	ppm	1421	---	---	---
Phosphorus	ppm	1192	---	---	---
Barium	ppm	1	---	---	---
Boron	ppm	110	---	---	---

**Depot:** CITREG  
**Unique No:** 5630627  
**Signed:** Wes Davis  
**Report Date:** 22 Aug 2023



# CONSTRUCTION EQUIPMENT



## VOLVO GRAPHS

