

CONSTRUCTION EQUIPMENT 376068 VOLVO L 120H 632703 - FRONT AXLE



Sample No: VCP353395 **Oil Type:** VOLVO WB 101

Job No: 376068

VOLVO	INFORMATIO	V		
	INFURMATIU			
Sample Number		VCP353395	VCP353104	
Sample Date		22 Aug 2023	23 Jan 2023	
Machine Hours		2325	1776	
Oil Hours		0	1776	
Oil Changed		Changed	Changed	
Sample Status		NORMAL	NORMAL	
VOLVO				
OIL CON	DITION			
Visc @ 40°C	cSt	50.3	□39.8	
VOLVO				
	MINATION			
Silicon	ppm	1 4	1 7	
Sodium	ppm	4	7	
Potassium	ppm	■<1	< 1	
WEAR N	AETAL C			
_	JE I ALS	·		
ron	ppm	■77	■323	
Copper	ppm	■ <1	2	
Lead	ppm	■0	- <1	
Tin	ppm	■ 0	0	
Aluminum	ppm	1	1	
Chromium	ppm	■2	9	
Molybdenum	ppm	2	1 3	
Vickel	ppm	■<1	2	
Titanium	ppm	0	<1	
Silver	ppm	0	0	
Manganese	ppm	4	1 4	
Vanadium	ppm	0	<1	
ADDITIV	JFS			
_	-	2745	T 4100	
Calcium	ppm	■3745	□ 4198	
Magnesium	ppm	16	12	
Zinc	ppm	1449	■ 1644	
Phosphorus	ppm	1227	1431	
Barium -	ppm	0	0	
Boron	ppm	111	117	



STRONGCO EQUIP (AB)

6 - 38403 BURNT LAKE TRAIL RED DEER COUNTY, AB CA T4S 2L4 Contact: Perry Doyle pdoyle@strongco.com T: (403)346-3473 F: (403)346-3487

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO9652Unique No:5631233Signed:Wes DavisReport Date:24 Aug 2023



CONSTRUCTION EQUIPMENT





