

CONSTRUCTION EQUIPMENT GFL 8-377629 VOLVO L120H 632507 - REAR AXLE



Sample No: VCP429981
Oil Type: NOT GIVEN
Job No: 8-377629

VOLVO	E INFORMATION			
			V(CD202420	
Sample Number		VCP429981	VCP382430	
Sample Date		08 Sep 2023	02 Feb 2023	
Machine Hours		17100	15090	
Oil Hours		0	0	
Oil Changed		Changed	Changed	
Sample Status		NORMAL	NORMAL	
VOLVO				
OIL CON	IDITION			
Visc @ 40°C	cSt	47.5	■82.7	
VOLVO				
CONTAI	MINATION			
Silicon	ppm	16	1 1	
Sodium	ppm	_ <1	1	
Potassium	ppm		П0	
	1-1-	_		
VOLVO				
WEAR I	METALS			
Iron	ppm	■32	■30	
Copper	ppm	■ <1	0	
Lead	ppm	0	0	
Tin	ppm	■ 0	0	
Aluminum	ppm	2	1	
Chromium	ppm	■<1	- <1	
Molybdenum	ppm	4	2	
Nickel	ppm	-<1	- <1	
Titanium	ppm	0	<1	
Silver	ppm	0	0	
Manganese	ppm	<1	<1	
Vanadium	ppm	0	0	
	•			
ADDITIV	VFS			
Calcium		4233	4416	
	ppm	4233 17	16	
Magnesium	ppm			
Zinc	ppm	1642	1687	
Phosphorus	ppm	1402	1422	
Barium	ppm	0	0	
Boron	ppm	122	124	



STRONGCO EQUIPMENT INC.

1640 ENTERPRISE ROAD MISSISSAUGA, ON CA L4W 4L4 Contact: Janice Cripps jcripps@strongco.com T: (905)565-3876 F: (905)670-2338

Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:SHEMISUnique No:5644011Signed:Kevin MarsonReport Date:15 Sep 2023



CONSTRUCTION EQUIPMENT





