

## CONSTRUCTION EQUIPMENT VOLVO EC46OCL 110437 - REAR LEFT FINAL DRIVE



Sample No: VCP117285

Oil Type: MOBIL MOBILUBE HD PLUS 85W140

Job No:

VOLVO	INFORMATIO	N		
	. INFURMATIU		<u>_</u>	
Sample Number		VCP117285		 
Sample Date		09 Aug 2011		 
Machine Hours		965		 
Oil Hours		500		 
Oil Changed		Changed		 
Sample Status		NORMAL		 
OIL CON	DITION			
Visc @ 40°C	cSt	<b>162.9</b>		 
COLVO	MINATION			
		NE C		
Water	%	NEG		 
Silicon	ppm	<b>12</b>		 
Sodium	ppm	■8		 
Potassium	ppm	<b>■</b> 0		 
VOLVO				
WEAR N	METALS			
Iron	ppm	<b>188</b>		 
Copper	ppm	<b>64</b>		 
Lead	ppm	<b>4</b>		 
Tin	ppm	<b>■</b> 0		 
Aluminum	ppm	<b>4</b>		 
Chromium	ppm	<b>6</b>		 
Molybdenum	ppm	<b>0</b>		 
Nickel	ppm	<1		 
Titanium	ppm	<1		 
Silver	ppm	0		 
Manganese	ppm	<b>7</b>		 
Vanadium	ppm	0		 
ADDITIV	IES			
Calcium	ppm	<b>1</b> 0		 
Magnesium	ppm	<b>4</b>		 
Zinc	ppm	<b>■37</b>		 
Phosphorus	ppm	<b>1031</b>		 
Barium	ppm	<b>160</b>		 
Boron	ppm	<u> </u>		 



MCCLUNG-LOGAN EQUIPMENT CO - RICHMOND
1345 MOUNTAIN ROAD
GLEN ALLEN, VA
US 23060
Contact: KYLE RATLIFFE
KRATLIFFE@MCCLUNG-LOGAN.COM
T:
F: (804)266-1611

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the component. The condition of the oil is acceptable for the time in service.

Depot:VOLVO8882Unique No:5651290Signed:Jonathan HesterReport Date:22 Aug 2011



## **CONSTRUCTION EQUIPMENT**





