

Sample No: VCP353415

Oil Type: VOLVO AUTOMATIC TRANSMISSION FLUID AT102

Job No: 8-382439

SAMPLE	E INFORMATION	N		
Sample Number		VCP353415	 	
Sample Date		24 Oct 2023	 	
Machine Hours		3463	 	
Oil Hours		0	 	
Oil Changed		Not Changd	 	
Sample Status		NORMAL	 	
OIL CON	IDITION			
Visc @ 40°C	cSt	29.6	 	
VOLVO				
CONTAN	MINATION			
Silicon	ppm	5	 	
Sodium	ppm	2	 	
Potassium	ppm	■0	 	
	ρρ			
VOLVO	METALC			
WEAR N	METAT2			
Iron	ppm	42	 	
Copper	ppm	■3	 	
Lead	ppm	■0	 	
Tin	ppm	■0	 	
Aluminum	ppm	■ 3	 	
Chromium	ppm	■<1	 	
Molybdenum	ppm	■3	 	
Nickel	ppm	■0	 	
Titanium	ppm	0	 	
Silver	ppm	■<1	 	
Manganese	ppm	- <1	 	
Vanadium	ppm	0	 	
VOLVO				
ADDITIV	VES			
Calcium	ppm	219	 	
Magnesium	ppm	47	 	
Zinc	ppm	102	 	
Phosphorus	ppm	■230	 	
Barium	ppm	<u> </u>	 	
Boron	ppm	67	 	
		_		



STRONGCO EQUIPMENT INC.

1640 ENTERPRISE ROAD MISSISSAUGA, ON CA L4W 4L4 Contact: Ed Knott eknott@strongco.com T: (905)670-5100 F: (905)670-7869

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot:SHEMISUnique No:5668880Signed:Wes DavisReport Date:25 Oct 2023

Contact/Location: Ed Knott - SHEMIS



CONSTRUCTION EQUIPMENT





