



CONSTRUCTION EQUIPMENT

BETON PROVINCIAL 382133 VOLVO L90F 69039 - TRANSMISSION (AUTO)



Sample No: VCP381763

Oil Type: DEXRON III

Job No: 382133



SAMPLE INFORMATION

Sample Number	VCP381763	---	---	---
Sample Date	23 Oct 2023	---	---	---
Machine Hours	17925	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Changed	---	---	---
Sample Status	NORMAL	---	---	---



STRONGCO EQUIPMENT INC (STE- FOY)

175, rue de Rotterdam
 St-Augustin-de-Desmaures, QC
 CA G3A 2K2
 Contact: Marc Dube
 mdube@strongco.com
 T:
 F: (418)870-1701



OIL CONDITION

Visc @ 40°C	cSt	■ 30.8	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Silicon	ppm	■ 4	---	---	---
Sodium	ppm	■ 2	---	---	---
Potassium	ppm	■ 0	---	---	---



WEAR METALS

Iron	ppm	■ 8	---	---	---
Copper	ppm	■ <1	---	---	---
Lead	ppm	■ <1	---	---	---
Tin	ppm	■ 0	---	---	---
Aluminum	ppm	■ 1	---	---	---
Chromium	ppm	■ 0	---	---	---
Molybdenum	ppm	■ 0	---	---	---
Nickel	ppm	■ 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	■ <1	---	---	---
Manganese	ppm	■ 0	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	25	---	---	---
Magnesium	ppm	■ 1	---	---	---
Zinc	ppm	■ 23	---	---	---
Phosphorus	ppm	■ 196	---	---	---
Barium	ppm	■ <1	---	---	---
Boron	ppm	■ 87	---	---	---

Diagnosis

Échantillonner de nouveau l'équipement au prochain intervalle de vidange afin d'en surveiller la condition. Le fluide n'était pas spécifié, toutefois, une comparaison avec d'autres fluides indiqua que ce fluide est du (GENERIC) DEXRON III. Veuillez confirmer. Les taux d'usure de tous les composants sont normaux. Il n'y a aucun indice de contamination dans le fluide. L'état de le fluide est acceptable pour la durée de service.

Depot: VOLVO0228
 Unique No: 5669515
 Signed: Wes Davis
 Report Date: 27 Oct 2023



CONSTRUCTION EQUIPMENT



VOLVO GRAPHS

