CONSTRUCTION EQUIPMENT 8-381499 VOLVOL180H 5658 - REAR AXLE



Sample No:	VCP393154
Oil Type:	NOT GIVEN
Job No:	8-381499

VOLVO

	E INFORMATION			
Sample Number	-	VCP393154	 	
Sample Date		12 Oct 2023	 	
Machine Hours		1010	 	
Oil Hours		0	 	
Oil Changed		N/A	 	
Sample Status		NORMAL	 	
OIL CON	DITION			
Visc @ 40°C	cSt	60.3	 	
VISC @ 40 C	CSL	00.5	 	
VOLVO			 	
CONTAI	MINATION			
Silicon	ppm	12	 	
Sodium	ppm	10	 	
Potassium	ppm	2	 	
WEAR N	AETAIS			
			 _	
Iron	ppm	48	 	
Copper	ppm	2	 	
Lead	ppm	 <1	 	
Tin	ppm	0	 	
Aluminum	ppm	1	 	
Chromium	ppm	2	 	
Molybdenum	ppm	■4	 	
Nickel	ppm	 <1	 	
Titanium	ppm	0	 	
Silver	ppm	<1	 	
Manganese	ppm	4	 	
Vanadium	ppm	0	 	
VOLVO				
	VES			
Calcium	ppm	4019	 	
Magnesium	ppm	1 1	 	
Zinc	ppm	1639	 	
Phosphorus	ppm	1319	 	
Barium	ppm	■ <1	 	
D				



STRONGCO EQUIPMENT INC.

1640 ENTERPRISE ROAD MISSISSAUGA, ON CA L4W 4L4 Contact: Janice Cripps jcripps@strongco.com T: (905)565-3876 F: (905)670-2338

Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is SAE 80 Wet Brake Transaxle Oil. Please confirm the oil type and grade, and specify the brand of the oil on your next sample.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:	SHEMIS
Unique No:	5671761
Signed:	Wes Davis
Report Date:	07 Nov 2023

114

ppm


Boron

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO



Report Id: SHEMIS [WCAMIS] 02594682 (Generated: 11/07/2023 15:49:27) Rev: 1

Contact/Location: Janice Cripps - SHEMIS