



CONSTRUCTION EQUIPMENT

TRIPLE M METAL 8000385851 VOLVO L260 1233 - TRANSMISSION (AUTO)



Sample No: VCP380081
Oil Type: DEXRON III
Job No: 8000385851



SAMPLE INFORMATION

| | | | | |
|---------------|--------------------|-------------|-----|-----|
| Sample Number | VCP380081 | VCP394980 | --- | --- |
| Sample Date | 04 Dec 2023 | 12 Jul 2023 | --- | --- |
| Machine Hours | 7547 | 4516 | --- | --- |
| Oil Hours | 0 | 0 | --- | --- |
| Oil Changed | Not Chngd | Changed | --- | --- |
| Sample Status | NORMAL | NORMAL | --- | --- |

STRONGCO EQUIPMENT (CE)

1051 Heritage Rd.
Burlington, ON
CA L7L 4Y1
Contact: Sue Hooton
shooton@strongco.com
T: (905)331-3835
F: (905)643-6077



OIL CONDITION

| | | | | | |
|-------------|-----|-------------|------|-----|-----|
| Visc @ 40°C | cSt | 28.0 | 25.9 | --- | --- |
|-------------|-----|-------------|------|-----|-----|



CONTAMINATION

| | | | | | |
|-----------|-----|--------------|-----|-----|-----|
| Water | % | NEG | NEG | --- | --- |
| Silicon | ppm | 5 | 10 | --- | --- |
| Sodium | ppm | 2 | 5 | --- | --- |
| Potassium | ppm | <1 | 1 | --- | --- |



WEAR METALS

| | | | | | |
|------------|-----|--------------|-----|-----|-----|
| PQ | | 3 | 0 | --- | --- |
| Iron | ppm | 187 | 282 | --- | --- |
| Copper | ppm | 5 | 8 | --- | --- |
| Lead | ppm | <1 | 0 | --- | --- |
| Tin | ppm | 0 | 0 | --- | --- |
| Aluminum | ppm | 1 | 3 | --- | --- |
| Chromium | ppm | 2 | 2 | --- | --- |
| Molybdenum | ppm | 0 | <1 | --- | --- |
| Nickel | ppm | <1 | <1 | --- | --- |
| Titanium | ppm | 0 | 0 | --- | --- |
| Silver | ppm | <1 | 0 | --- | --- |
| Manganese | ppm | 3 | 8 | --- | --- |
| Vanadium | ppm | 0 | 0 | --- | --- |



ADDITIVES

| | | | | | |
|------------|-----|--------------|-----|-----|-----|
| Calcium | ppm | 380 | 91 | --- | --- |
| Magnesium | ppm | 2 | 1 | --- | --- |
| Zinc | ppm | 135 | 20 | --- | --- |
| Phosphorus | ppm | 266 | 175 | --- | --- |
| Barium | ppm | <1 | 4 | --- | --- |
| Boron | ppm | 74 | 47 | --- | --- |

Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) DEXRON III. Please confirm. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot: VOLVO0252
Unique No: 5694083
Signed: Kevin Marson
Report Date: 07 Dec 2023



CONSTRUCTION EQUIPMENT



GRAPHS

