Sample No:
 VCP370794

 Oil Type:
 NOT GIVEN

 Job No:
 SL23-089

VOLVO

VOLVO				
SAMPLE	<b>INFORMATION</b>			
Sample Number		VCP370794		 
Sample Date		15 Nov 2023		 
Machine Hours		502		 
Oil Hours		502		 
Oil Changed		Changed		 
Sample Status		NORMAL		 
OIL CON				
Visc @ 40°C		171	<u>.</u>	
VISC @ 40 C	cSt	171		 
VOLVO				 
CONTAM	AINATION			
Water	%	NEG		 
Silicon	ppm	39		 
Sodium	ppm	3		 
Potassium	ppm	2		 
WEAR N	AETAI C			
Iron	ppm	297		 
Copper	ppm	□ <1		 
Lead	ppm	0		 
Tin	ppm	0		 
Aluminum	ppm	8		 
Chromium	ppm	<b>4</b>		 
Molybdenum	ppm	0		 
Nickel	ppm	■ <1		 
Titanium	ppm	0		 
Silver	ppm	<1		 
Manganese	ppm	4		 
Vanadium	ppm	0		 

ADDITIVES									
Calcium	ppm	12							
Magnesium	ppm	2							
Zinc	ppm	9							
Phosphorus	ppm	296							
Barium	ppm	1							
Boron	ppm	<1							

## **GREAT WEST EQUIPMENT**

P.O. BOX 6067, 12623 CHARLIE LAKE FRONTAGE RD FORT ST. JOHN, BC CA V1J 2B0 Contact: Mathew Stockley mstockley@gwequipmnet.com T: (250)785-4223 F: (250)785-4237

## Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.


Depot:VOLVO5076Unique No:5694396Signed:Bill QuesnelReport Date:07 Dec 2023

## **CONSTRUCTION EQUIPMENT**



GRAPHS

VOLVO



Report Id: VOLVO5076 [WCAMIS] 02601311 (Generated: 12/07/2023 11:27:11) Rev: 1

Contact/Location: Mathew Stockley - VOLVO5076