



CONSTRUCTION EQUIPMENT

STELLA JONES 6203 - TRANSMISSION (AUTO)



Sample No: VCP380166
Oil Type: VOLVO AUTOMATIC TRANSMISSION FLUID AT102
Job No:



SAMPLE INFORMATION

Sample Number	VCP380166	---	---	---
Sample Date	30 Nov 2023	---	---	---
Machine Hours	12931	---	---	---
Oil Hours	0	---	---	---
Oil Changed	N/A	---	---	---
Sample Status	NORMAL	---	---	---

GREAT WEST EQUIPMENT
 1600 KOSMINA ROAD, 123 L&A CROSS RD
 VERNON, BC
 CA V1T 8T2
 Contact: Sarah Lawrence
 slawrence@gwequipment.com
 T: (866)627-2357
 F: (250)549-3397



OIL CONDITION

Visc @ 40°C	cSt	█ 28.5	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 3	---	---	---
Sodium	ppm	█ 2	---	---	---
Potassium	ppm	█ 2	---	---	---



WEAR METALS

Iron	ppm	█ 43	---	---	---
Copper	ppm	█ 2	---	---	---
Lead	ppm	█ <1	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ <1	---	---	---
Chromium	ppm	█ 0	---	---	---
Molybdenum	ppm	█ 0	---	---	---
Nickel	ppm	█ <1	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	█ <1	---	---	---
Manganese	ppm	█ 0	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	79	---	---	---
Magnesium	ppm	█ 1	---	---	---
Zinc	ppm	7	---	---	---
Phosphorus	ppm	█ 184	---	---	---
Barium	ppm	█ <1	---	---	---
Boron	ppm	█ 83	---	---	---

Diagnosis

Confirm the source of the lubricant being utilized for top-up/fill. Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. Additive levels indicate the addition of a different brand, or type of fluid. The condition of the fluid is acceptable for the time in service.

Depot: MARVER
Unique No: 5695976
Signed: Wes Davis
Report Date: 13 Dec 2023



CONSTRUCTION EQUIPMENT



GRAPHS

