



CONSTRUCTION EQUIPMENT

8000387798 VOLVO L80H 15727 - TRANSMISSION (AUTO)



Sample No: VCP392153
Oil Type: VOLVO AUTOMATIC TRANSMISSION FLUID AT102
Job No: 8000387798



SAMPLE INFORMATION

Sample Number	VCP392153	---	---	---
Sample Date	14 Dec 2023	---	---	---
Machine Hours	2544	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---

STRONGCO EQUIPMENT INC.
 1640 ENTERPRISE ROAD
 MISSISSAUGA, ON
 CA L4W 4L4
 Contact: Janice Cripps
 jcripps@strongco.com
 T: (905)565-3876
 F: (905)670-2338



OIL CONDITION

Visc @ 40°C	cSt	█ 28.2	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 12	---	---	---
Sodium	ppm	█ 6	---	---	---
Potassium	ppm	█ 1	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.



WEAR METALS

Iron	ppm	█ 97	---	---	---
Copper	ppm	█ 10	---	---	---
Lead	ppm	█ <1	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ 1	---	---	---
Chromium	ppm	█ <1	---	---	---
Molybdenum	ppm	█ <1	---	---	---
Nickel	ppm	█ <1	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	█ <1	---	---	---
Manganese	ppm	█ 9	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	█ 180	---	---	---
Magnesium	ppm	█ 2	---	---	---
Zinc	ppm	█ 81	---	---	---
Phosphorus	ppm	█ 214	---	---	---
Barium	ppm	█ 3	---	---	---
Boron	ppm	█ 61	---	---	---

Depot: SHEMIS
Unique No: 5696623
Signed: Wes Davis
Report Date: 15 Dec 2023



CONSTRUCTION EQUIPMENT



VOLVO GRAPHS

