



CONSTRUCTION EQUIPMENT

IMPACT AUTO 388500 VOLVO L90H 625974 - FRONT AXLE



Sample No: VCP394413
Oil Type: VOLVO WB 101
Job No: 388500



SAMPLE INFORMATION

Sample Number	VCP394413	---	---	---
Sample Date	14 Dec 2023	---	---	---
Machine Hours	4045	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

STRONGCO EQUIPMENT-EDMONTON

25616 117 Ave NW

Acheson, AB

CA T7X 6C2

Contact: Jonathan Morton

jmorton@strongco.com

T: (780)464-1909

F: (780)464-0434



OIL CONDITION

Visc @ 40°C	cSt	█ 42.8	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 11	---	---	---
Sodium	ppm	█ 8	---	---	---
Potassium	ppm	█ 0	---	---	---



WEAR METALS

Iron	ppm	█ 52	---	---	---
Copper	ppm	█ 6	---	---	---
Lead	ppm	█ <1	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ 1	---	---	---
Chromium	ppm	█ 1	---	---	---
Molybdenum	ppm	█ 2	---	---	---
Nickel	ppm	█ <1	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	<1	---	---	---
Manganese	ppm	█ 3	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	█ 4136	---	---	---
Magnesium	ppm	█ 11	---	---	---
Zinc	ppm	█ 1585	---	---	---
Phosphorus	ppm	█ 1311	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 114	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VOLVO3908

Unique No: 5696674

Signed: Wes Davis

Report Date: 15 Dec 2023



CONSTRUCTION EQUIPMENT



GRAPHS

