



CONSTRUCTION EQUIPMENT

2315189 VOLVO L110H 631855 - FRONT AXLE



Sample No: VCP392312
Oil Type: VOLVO WB 102
Job No: 2315189



SAMPLE INFORMATION

Sample Number	VCP392312	---	---	---
Sample Date	13 Dec 2023	---	---	---
Machine Hours	11402	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

MIRAGE

1255, 98 RUE
SAINT GEORGE, QC
CA G5Y 8J5
Contact: Yanick Tanguay-morin
yanick.tanguaymorin@boa-franc.com
T: (418)227-1181
F:



OIL CONDITION

Visc @ 40°C	cSt	█ 42.7	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 9	---	---	---
Sodium	ppm	█ 2	---	---	---
Potassium	ppm	█ 0	---	---	---



WEAR METALS

Iron	ppm	█ 13	---	---	---
Copper	ppm	█ 3	---	---	---
Lead	ppm	█ <1	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ 2	---	---	---
Chromium	ppm	█ 0	---	---	---
Molybdenum	ppm	█ <1	---	---	---
Nickel	ppm	█ <1	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ 0	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	█ 3936	---	---	---
Magnesium	ppm	█ 16	---	---	---
Zinc	ppm	█ 1562	---	---	---
Phosphorus	ppm	█ 1316	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 113	---	---	---

Diagnosis

Échantillonner de nouveau l'équipement au prochain intervalle de vidange afin d'en surveiller la condition. Les taux d'usure de tous les composants sont normaux. Il n'y a aucun indice de contamination dans l'huile. L'état de l'huile est acceptable pour la durée de service.

Depot: MIRSAI
Unique No: 5698549
Signed: Wes Davis
Report Date: 28 Dec 2023



CONSTRUCTION EQUIPMENT



GRAPHS

