



CONSTRUCTION EQUIPMENT

2315188 VOLVO L110H 632455 - REAR AXLE



Sample No: VCP347075
Oil Type: VOLVO WB 102
Job No: 2315188



SAMPLE INFORMATION

Sample Number	VCP347075	---	---	---
Sample Date	05 Dec 2023	---	---	---
Machine Hours	4095	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

MIRAGE
 1255, 98 RUE
 SAINT GEORGE, QC
 CA G5Y 8J5
 Contact: Yanick Tanguay-morin
 yanick.tanguaymorin@boa-franc.com
 T: (418)227-1181
 F:



OIL CONDITION

Visc @ 40°C	cSt	█ 42.2	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 12	---	---	---
Sodium	ppm	█ 1	---	---	---
Potassium	ppm	█ <1	---	---	---



WEAR METALS

Iron	ppm	█ 46	---	---	---
Copper	ppm	█ 1	---	---	---
Lead	ppm	█ <1	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ 1	---	---	---
Chromium	ppm	█ <1	---	---	---
Molybdenum	ppm	█ <1	---	---	---
Nickel	ppm	█ <1	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ 1	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	█ 3847	---	---	---
Magnesium	ppm	█ 10	---	---	---
Zinc	ppm	█ 1547	---	---	---
Phosphorus	ppm	█ 1313	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 109	---	---	---

Diagnosis
 Échantillonner de nouveau l'équipement au prochain intervalle de vidange afin d'en surveiller la condition. Les taux d'usure de tous les composants sont normaux. Il n'y a aucun indice de contamination dans l'huile. L'état de l'huile est acceptable pour la durée de service.

Depot: MIRSAI
Unique No: 5698550
Signed: Wes Davis
Report Date: 28 Dec 2023



VOLVO GRAPHS

