

## **CONSTRUCTION EQUIPMENT**

VOLVO L220H 3315 - DIESEL EXHAUST FLUID (DEF)

Sample No: VCP297740

Oil Type: **DEF** (Diesel Exaust Fluid)

Job No: 390399

SAMPLE INFORMATION					
24MLTE II	AF URMA HUN				_
Sample Number		VCP297740			
Sample Date		09 Jan 2024			
Machine Hours		8999			
Oil Hours		0			
Oil Changed		Changed			
Sample Status		ABNORMAL			
CONTAMIN	MULTUR				
LUNTAMII	MATIUN				
Hydrocarbon	scalar	<b>■</b> NONE			
DEF CONDITION					
Urea Content	%	■32.1			
Density @ 20°C	g/cm3	▲ 1.0860			
Refracting Index	9, 55	■1.3821			
Appearance	scalar	Clear & Bright			
Appearance	Jediai	Cicai & Drigit			



#### STRONGCO INC

1730 RUE DE L'HYDRO VAL D'OR, QC CA J9P 6Z2 Contact: Kevens Morneau kmorneau@strongco.com T:

F: (819)825-1360

### Diagnosis

Fluid does not meet ISO 22241-2 requirements. Contact supplier.{not applicable) There is no indication of any contamination in the diesel exhaust fluid (def). Density is low.

Depot: VOLVO0229 **Unique No:** 5709743 Signed: Kevin Marson Report Date: 15 Jan 2024





# **CONSTRUCTION EQUIPMENT**





#### GRAPHS





Report Id: VOLVO0229 [WCAMIS] 02608657 (Generated: 01/15/2024 17:02:38) Rev: 1