



CONSTRUCTION EQUIPMENT

MATREC GFL RIMOUSKI VOLVO L90F 68287 - REAR AXLE



Sample No: VCP391981
Oil Type: VOLVO WB 102
Job No:



SAMPLE INFORMATION

Sample Number	VCP391981	VCP392099	---	---
Sample Date	20 Dec 2023	19 May 2023	---	---
Machine Hours	7507	10123	---	---
Oil Hours	0	0	---	---
Oil Changed	Changed	Changed	---	---
Sample Status	NORMAL	NORMAL	---	---

STRONGCO EQUIPMENT INC (STE- FOY)

175, rue de Rotterdam
 St-Augustin-de-Desmaures, QC
 CA G3A 2K2
 Contact: Michel Lepage
 mlepage@strongco.com
 T: (418)870-1700
 F: (418)870-1701



OIL CONDITION

Visc @ 40°C	cSt	43.0	41.1	---	---
-------------	-----	-------------	------	-----	-----



CONTAMINATION

Water	%	NEG	NEG	---	---
Silicon	ppm	16	21	---	---
Sodium	ppm	<1	1	---	---
Potassium	ppm	<1	3	---	---



WEAR METALS

Iron	ppm	13	97	---	---
Copper	ppm	1	17	---	---
Lead	ppm	0	<1	---	---
Tin	ppm	0	2	---	---
Aluminum	ppm	2	2	---	---
Chromium	ppm	0	<1	---	---
Molybdenum	ppm	0	0	---	---
Nickel	ppm	<1	<1	---	---
Titanium	ppm	0	<1	---	---
Silver	ppm	0	0	---	---
Manganese	ppm	0	1	---	---
Vanadium	ppm	0	<1	---	---



ADDITIVES

Calcium	ppm	4215	4487	---	---
Magnesium	ppm	15	13	---	---
Zinc	ppm	1617	1765	---	---
Phosphorus	ppm	1337	1490	---	---
Barium	ppm	0	0	---	---
Boron	ppm	121	127	---	---

Diagnosis

Échantillonner de nouveau l'équipement au prochain intervalle de vidange afin d'en surveiller la condition. Les taux d'usure de tous les composants sont normaux. Il n'y a aucun indice de contamination dans l'huile. L'état de l'huile est acceptable pour la durée de service.

Depot: VOLVO0228
Unique No: 5709847
Signed: Wes Davis
Report Date: 15 Jan 2024



CONSTRUCTION EQUIPMENT



GRAPHS

