



CONSTRUCTION EQUIPMENT

ROSARIO POIRIEU VOLVO L110H 632632 - FRONT AXLE



Sample No: VCP380328

Oil Type: TRANSAXLE OIL SAE 75W80

Job No:



SAMPLE INFORMATION

Sample Number	VCP380328	---	---	---
Sample Date	18 Dec 2023	---	---	---
Machine Hours	866	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

STRONGCO EQUIPMENT INC (STE- FOY)

175, rue de Rotterdam
 St-Augustin-de-Desmaures, QC
 CA G3A 2K2
 Contact: Marc Dube
 mdube@strongco.com
 T:
 F: (418)870-1701



OIL CONDITION

Visc @ 40°C	cSt	█41.6	---	---	---
-------------	-----	-------	-----	-----	-----



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█32	---	---	---
Sodium	ppm	█2	---	---	---
Potassium	ppm	█2	---	---	---



WEAR METALS

Iron	ppm	█317	---	---	---
Copper	ppm	█1	---	---	---
Lead	ppm	█0	---	---	---
Tin	ppm	█0	---	---	---
Aluminum	ppm	█2	---	---	---
Chromium	ppm	█8	---	---	---
Molybdenum	ppm	█18	---	---	---
Nickel	ppm	█2	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█17	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	█4104	---	---	---
Magnesium	ppm	█14	---	---	---
Zinc	ppm	█1598	---	---	---
Phosphorus	ppm	█1373	---	---	---
Barium	ppm	█0	---	---	---
Boron	ppm	█116	---	---	---

Diagnosis

Échantillonner de nouveau l'équipement au prochain intervalle de vidange afin d'en surveiller la condition. Le fluide n'était pas spécifié, toutefois, une comparaison avec d'autres fluides indique que ce fluide est du (GENERIC) TRANSAXLE OIL SAE 75W80. Veuillez confirmer. Les taux d'usure de tous les composants sont normaux. Il n'y a aucun indice de contamination dans l'huile. L'état de l'huile est acceptable pour la durée de service.

Depot: VOLVO0228
 Unique No: 5709855
 Signed: Wes Davis
 Report Date: 15 Jan 2024



CONSTRUCTION EQUIPMENT



VOLVO GRAPHS

