



# CONSTRUCTION EQUIPMENT

C BELANGER 392182 VOLVO L70H 626049 - TRANSMISSION (AUTO)



**Sample No:** VCP380345  
**Oil Type:** VOLVO AT 102  
**Job No:** 392182



## SAMPLE INFORMATION

Sample Number	VCP380345	---	---	---
Sample Date	18 Jan 2024	---	---	---
Machine Hours	92	---	---	---
Oil Hours	92	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	ATTENTION	---	---	---

### STRONGCO EQUIPMENT INC (STE- FOY)

175, rue de Rotterdam  
St-Augustin-de-Desmaures, QC  
CA G3A 2K2  
Contact: Michel Lepage  
mlepage@strongco.com  
T: (418)870-1700  
F: (418)870-1701



## OIL CONDITION

Visc @ 40°C	cSt	■ 32.1	---	---	---
-------------	-----	--------	-----	-----	-----



## CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	■ 6	---	---	---
Sodium	ppm	■ 2	---	---	---
Potassium	ppm	■ 2	---	---	---



## WEAR METALS

Iron	ppm	■ 20	---	---	---
Copper	ppm	■ 4	---	---	---
Lead	ppm	■ <1	---	---	---
Tin	ppm	■ 0	---	---	---
Aluminum	ppm	■ <1	---	---	---
Chromium	ppm	■ <1	---	---	---
Molybdenum	ppm	■ 0	---	---	---
Nickel	ppm	■ <1	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	■ 0	---	---	---
Manganese	ppm	■ 5	---	---	---
Vanadium	ppm	0	---	---	---



## ADDITIVES

Calcium	ppm	▲ 78	---	---	---
Magnesium	ppm	■ 2	---	---	---
Zinc	ppm	■ 116	---	---	---
Phosphorus	ppm	■ 222	---	---	---
Barium	ppm	■ 1	---	---	---
Boron	ppm	■ 53	---	---	---

### Diagnosis

Confirm the source of the lubricant being utilized for top-up/fill. Échantillonner de nouveau l'équipement au prochain intervalle de vidange afin d'en surveiller la condition. Les taux d'usure de tous les composants sont normaux. Il n'y a aucun indice de contamination dans le fluide. Les niveaux d'additifs indiquent l'ajout d'une autre marque ou d'un autre type d'huile. L'état de le fluide est acceptable pour la durée de service.

**Depot:** VOLVO0228  
**Unique No:** 5711429  
**Signed:** Kevin Marson  
**Report Date:** 23 Jan 2024



# CONSTRUCTION EQUIPMENT



## VOLVO GRAPHS

