

CONSTRUCTION EQUIPMENT 368304 VOLVO EW220E 323074 - FRONT AXLE



Sample No: VC458402

Oil Type: VOLVO API GL-5 SAE 75W90

Job No: 368304

SAMPLE	INFORMATION				
Sample Number		VC458402			
Sample Date		09 Jan 2024			
Machine Hours		2032			
Oil Hours		2032			
Oil Changed		Not Changd			
Sample Status		NORMAL			
OIL CONDITION					
Visc @ 40°C	cSt	52.9			
CONTAMINATION					
Water	%	NEG			
Silicon	ppm	■8			
Sodium	ppm	16			
Potassium	ppm	2			
VOLVO					
WEAR METALS					
Iron	ppm	10			
Copper	ppm	5			
Lead	ppm	 <1			
Tin	ppm	■ 0			
Aluminum	ppm	1			
Chromium	ppm	■ <1			
Molybdenum	ppm	0			
Nickel	ppm	■ <1			
Titanium	ppm	0			
Silver	ppm	0			
Manganese	ppm	5			
Vanadium	ppm	0			
ADDITIVES					
Calcium	ppm	3498			
Magnesium	ppm	10			
Zinc	ppm	1373			
Phosphorus	ppm	1133			
Barium	ppm	■<1			
Boron	ppm	100			

CITY OF REGINA - FLEET SERVICES DEPT

2476 VICTORIA AVENUE, BOX 1790 REGINA, SK CA S4P 3C8 Contact: Curtis Jors cjors@regina.ca

T: (306)777-7674 F: (306)777-6813

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:CITREGUnique No:5720994Signed:Wes DavisReport Date:30 Jan 2024

Contact/Location: Curtis Jors - CITREG



CONSTRUCTION EQUIPMENT





