CONSTRUCTION EQUIPMENT 368520 VOLVO L 150H 150HL00006998 - FRONT AXLE



VOLVO

	E INFORMATION				
Sample Number		VC458405			
Sample Date		11 Jan 2024			
Machine Hours		6947			
Oil Hours		0			
Oil Changed		Not Changd			
Sample Status		NORMAL			
OIL CON					
			<u>-</u>	_	
Visc @ 40°C	cSt	54.2			
VOLVO					
CONTAN	MINATION				
Water	%	NEG			
Silicon		■ 14			
Sodium	ppm	1 4			
	ppm				
Potassium	ppm	■ <1			
VOLVO					
VEAR N	METALS				
Iron	ppm	15			
Copper	ppm	□ <1			
Lead	ppm	 <1			
Tin	ppm	0			
Aluminum	ppm	1			
Chromium	ppm	■ <1			
Molybdenum					
Nickel	ppm	■ 0			
Titanium	ppm	0			
Silver	ppm				
	ppm	0			
Manganese	ppm	0			
Vanadium	ppm	0			
VOLVO					
ADDITI\	VES				
Calcium	maa	3685			

Calcium	ppm	3685	 	
Magnesium	ppm	1 9	 	
Zinc	ppm	1472	 	
Phosphorus	ppm	1195	 	
Barium	ppm	0	 	
Boron	ppm	105	 	



CITY OF REGINA - FLEET SERVICES DEPT

2476 VICTORIA AVENUE, BOX 1790 REGINA, SK CA S4P 3C8 Contact: Curtis Jors cjors@regina.ca T: (306)777-7674 F: (306)777-6813

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:	CITREG		
Unique No:	5720995		
Signed:	Wes Davis		
Report Date:	30 Jan 2024		


Contact/Location: Curtis Jors - CITREG

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO



Report Id: CITREG [WCAMIS] 02611900 (Generated: 01/30/2024 10:41:25) Rev: 1