

CONSTRUCTION EQUIPMENT 368304 VOLVO EW220E 323074 - REAR AXLE



Sample No: VC458403

Oil Type: VOLVO API GL-5 SAE 75W90

Job No: 368304

INFORMATION				
_				
	2032			
	Not Changd			
	NORMAL			
ITION				
				_
cSt	52.4			
INATION				
	NEG			
	_			
T. F.	_			
TALC				
FIAL2				
ppm	■9			
ppm	24			
ppm				
ppm	■0			
ppm	1			
ppm	_			
ppm	■0			
ppm	■ <1			
ppm				
ppm	-			
	_			
ppm	0			
23				
ppm	3388			
ppm	9			
ppm	1367			
ppm	11116			
	■1116 ■2			
	ITION cSt INATION % ppm ppm ppm ppm ppm ppm ppm	Not Changd NORMAL NORMAL	VC458403 09 Jan 2024 2032 2032 Not Changd NORMAL ITION CSt 52.4 Ppm 5 Ppm 18 Ppm 24 Ppm 24 Ppm 24 Ppm 30 Ppm 10 Ppm 10 Ppm 10 Ppm 0	VC458403

CITY OF REGINA - FLEET SERVICES DEPT

2476 VICTORIA AVENUE, BOX 1790 REGINA, SK CA S4P 3C8 Contact: Curtis Jors cjors@regina.ca T: (306)777-7674 F: (306)777-6813

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:CITREGUnique No:5720997Signed:Wes DavisReport Date:30 Jan 2024

Contact/Location: Curtis Jors - CITREG



CONSTRUCTION EQUIPMENT





