

CONSTRUCTION EQUIPMENT
FONDERIE HORNE 8000392189 VOLVO ECR145EL 311565 - SWIN

Sample No: VCP392411

Oil Type: VOLVO API GL-5 SAE 75W90

Job No: 8000392189

SAMPLE INFORMATION					
Sample Number		VCP392411			
Sample Date		27 Jan 2024			
Machine Hours		11176			
Oil Hours		0			
Oil Changed		Not Changd			
Sample Status		ABNORMAL			
OIL CONDITION					
Visc @ 40°C	cSt	136			
VOLVO					
CONTAMINATION					
Water	%	NEG			
Silicon	ppm	■8			
Sodium	ppm	1			
Potassium	ppm	1			
		_			
WEAR METALS					
_		-21			
Iron	ppm	■21			
Copper Lead	ppm	7			
	ppm	1			
Tin Aluminum	ppm	0			
Chromium	ppm	□ <1 □ 0			
Molybdenum	ppm	0			
Nickel	ppm	■ < 1			
Titanium	ppm	0			
Silver	ppm	0			
Manganese	ppm	0			
Vanadium	ppm	0			
variacium	ppiii	U			
VOLVO					
ADDITIVI	22				
Calcium	ppm	91			
Magnesium	ppm	3			
Zinc	ppm	123			
Phosphorus	ppm	982			
Barium	ppm	0			
Boron	ppm	113			



STRONGCO INC

1730 RUE DE L'HYDRO VAL D'OR, QC CA J9P 6Z2 Contact: Stephan Constant sconstant@strongco.com T: F: (819)825-1360

Diagnosis

We advise that you check for the source of water entry. We recommend that you drain the oil from the component if this has not already been done. We recommend an early resample to monitor this condition.All component wear rates are normal. There is a moderate concentration of water present in the oil. Free water present. The oil is no longer serviceable due to the presence of contaminants.

Depot: VOLVO0229 **Unique No:** 5722011 Signed: Bill Quesnel Report Date: 01 Feb 2024



CONSTRUCTION EQUIPMENT





GRAPH

