



CONSTRUCTION EQUIPMENT

VALBRUNA 393582 VOLVO L150H 7150 - TRANSMISSION (AUTO)



Sample No: VCP450292
Oil Type: DEXRON III
Job No: 393582



SAMPLE INFORMATION

Sample Number	VCP450292	---	---	---
Sample Date	02 Feb 2024	---	---	---
Machine Hours	2059	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---

STRONGCO EQUIPMENT (CE)

1051 Heritage Rd.
Burlington, ON
CA L7L 4Y1
Contact: Sue Hooton
shooton@strongco.com
T: (905)331-3835
F: (905)643-6077



OIL CONDITION

Visc @ 40°C	cSt	█ 28.1	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 6	---	---	---
Sodium	ppm	█ 3	---	---	---
Potassium	ppm	█ 2	---	---	---



WEAR METALS

Iron	ppm	█ 45	---	---	---
Copper	ppm	█ 6	---	---	---
Lead	ppm	█ <1	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ 1	---	---	---
Chromium	ppm	█ <1	---	---	---
Molybdenum	ppm	█ 0	---	---	---
Nickel	ppm	█ <1	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	█ 0	---	---	---
Manganese	ppm	█ 3	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	█ 198	---	---	---
Magnesium	ppm	█ 2	---	---	---
Zinc	ppm	█ 65	---	---	---
Phosphorus	ppm	█ 230	---	---	---
Barium	ppm	█ 4	---	---	---
Boron	ppm	█ 72	---	---	---

Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) DEXRON III. Please confirm. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot: VOLVO0252
Unique No: 5724151
Signed: Wes Davis
Report Date: 13 Feb 2024



CONSTRUCTION EQUIPMENT



VOLVO GRAPHS

