

Sample No: VCP392812
Oil Type: VOLVO WB 102

Job No: 396718

VOLVO	INFORMATION	ı		
	. IMI UMPIATIUI			_
Sample Number		VCP392812		
Sample Date		07 Mar 2024		
Machine Hours		4722		
Oil Hours		4000		
Oil Changed		Changed		
Sample Status		NORMAL		
OIL CON	NITION			
Visc @ 40°C	cSt	42.7		
VOLVO				
CONTAN	MINATION			
Water	%	NEG	-	
Silicon				
	ppm	■17		
Sodium	ppm	4		
Potassium	ppm	■2		
VOLVO				
WEAR N	METALS			
Iron	ppm	■28		
Copper	ppm	24		
Lead	ppm	 <1		
Tin	ppm	■0		
Aluminum	ppm	1		
Chromium	ppm	 <1		
Molybdenum	ppm	0		
Nickel	ppm	6		
Titanium	ppm	0		
Silver	ppm	0		
Manganese	ppm	■ 0		
Vanadium	ppm	0		
Variadiani	ppiii	· ·		
VOLVO				
ADDITIV	/EZ			
Calcium	ppm	■3558		
Magnesium	ppm	■7		
Zinc	ppm	1500		
Phosphorus	ppm	1339		
Barium	ppm	■0		
Boron	ppm	106		



STRONGCO EQUIPMENT (CE)

1051 Heritage Rd.
Burlington, ON
CA L7L 4Y1
Contact: Sue Hooton
shooton@strongco.com
T: (905)331-3835
F: (905)643-6077

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO0252Unique No:5746703Signed:Wes DavisReport Date:12 Mar 2024



CONSTRUCTION EQUIPMENT





