CONSTRUCTION EQUIPMENT TRIPLE M METAL 396718 VOLVO A40G 353438 - FRONT LEFT FINA

Sample No: VCP450383 **Oil Type:** VOLVO WB 102 Job No: 396718

CONTAMINATION

%

ppm

Water

Silicon

VOLVO

VOLVO						
SAMPLE IN	FORMATION					
Sample Number		VCP450383				
Sample Date		07 Mar 2024				
Machine Hours		4722				
Oil Hours		4000				
Oil Changed		Changed				
Sample Status		NORMAL				
OIL CONDITION						
Visc @ 40°C	cSt	42.8				
VOLVO						

NEG

18



STRONGCO EQUIPMENT (CE)

1051 Heritage Rd. Burlington, ON CA L7L 4Y1 Contact: Sue Hooton shooton@strongco.com T: (905)331-3835 F: (905)643-6077

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Sodium	ppm	5	 	
Potassium	ppm	2	 	
VOLVO				
WLAR I	METALS			
Iron	ppm	29	 	
Copper	ppm	24	 	
Lead	ppm	1	 	
Tin	ppm	0	 	
Aluminum	ppm	∎1	 	
Chromium	ppm		 	
Molybdenum	ppm	0	 	
Nickel	ppm	6	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	0	 	
Vanadium	ppm	0	 	

VOLVO **ADDITIVES** Calcium 3610 ppm Magnesium 8 ppm Zinc ppm **1531** Phosphorus 1356 ppm Barium ppm 0 🔲 Boron ppm **107**


> Depot: VOLVO0252 Unique No: 5746709 Signed: Wes Davis Report Date: 12 Mar 2024

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO



Report Id: VOLVO0252 [WCAMIS] 02621590 (Generated: 03/12/2024 15:31:02) Rev: 1

Contact/Location: Crane - Sue Hooton - VOLVO0252