

# CONSTRUCTION EQUIPMENT 551087 VOLVO L260H 1376 - FRONT AXLE



Sample No: VCP450441

Oil Type: VOLVO WB 102

**Job No:** 551087

SAMPLE	INFORMATION			
Sample Number		VCP450441	 	
Sample Date		15 Mar 2024	 	
Machine Hours		1070	 	
Oil Hours		1070	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
OIL CON	NITION			
Visc @ 40°C	cSt	<b>42.1</b>	 	
VOLVO				
CONTAN	MINATION			
Water	%	NEG	 	
Silicon	ppm	<b>13</b>	 	
Sodium	ppm	<b>2</b>	 	
Potassium	ppm	■3	 	
	I. I.			
VOLVO	AFTALC			
WEAR N	NE I ALS			
Iron	ppm	<b>190</b>	 	
Copper	ppm	■1	 	
Lead	ppm	<b>0</b>	 	
Tin	ppm	■0	 	
Aluminum	ppm	<b>1</b>	 	
Chromium	ppm	■3	 	
Molybdenum	ppm	<b>1</b>	 	
Nickel	ppm	<b>1</b>	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	■3	 	
Vanadium	ppm	0	 	
VOLVO			 	
ADDITIV	<b>IES</b>			
Calcium	ppm	■3886	 	
Magnesium	ppm	 8	 	
Zinc	ppm	■1573	 	
Phosphorus	ppm	<b>1343</b>	 	
Barium	ppm	<b>0</b>	 	
Boron	ppm	<b>110</b>	 	

#### STRONGCO EQUIP (AB)

6 - 38403 BURNT LAKE TRAIL RED DEER COUNTY, AB CA T4S 2L4 Contact: Perry Doyle pdoyle@strongco.com T: (403)391-3520 F: (403)346-3487

### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO9652Unique No:5748228Signed:Wes DavisReport Date:19 Mar 2024



## **CONSTRUCTION EQUIPMENT**





#### GRAPH

