

## **CONSTRUCTION EQUIPMENT**



Oil Type: VOLVO SUPER HYDRAULIC OIL 46

**Job No:** 8000398340

CAMDI E II	NFORMATION			
	II UNIMATION			
Sample Number		VCP392187	 	
Sample Date		20 Mar 2024	 	
Machine Hours		4145	 	
Oil Hours		0	 	
Oil Changed		Not Changd	 	
Sample Status		NORMAL	 	
OIL CONDI	TION			
OIL CONDI	TIUN			
Visc @ 40°C	cSt	<b>41.5</b>	 	
VOLVO	IATION			

CONTA	MINATION			
Water	%	NEG	 	
Particles >4µm		<b>16206</b>	 	
Particles >6µm		<b>1904</b>	 	
Particles >14µm	n	<b>66</b>	 	
ISO 4406:1999 (	(c)	21/18/13	 	
Silicon	ppm	<b>4</b>	 	
Sodium	ppm	<b>1</b>	 	
Potassium	ppm	<b>■</b> <1	 	

WEAR METALS					
Iron	ppm	<b>11</b>			
Copper	ppm	■33			
Lead	ppm	<b>0</b>			
Tin	ppm	■0			
Aluminum	ppm	<b>-&lt;1</b>			
Chromium	ppm	■0			
Molybdenum	ppm	<b>0</b>			
Nickel	ppm	■0			
Titanium	ppm	0			
Silver	ppm	0			
Manganese	ppm	<b>0</b>			
Vanadium	ppm	0			

ADDITIVES					
Calcium	ppm	■37			
Magnesium	ppm	<b>1</b>			
Zinc	ppm	■385			
Phosphorus	ppm	■363			
Barium	ppm	<b>□</b> 0			
Boron	ppm	<b>■&lt;1</b>			



#### STRONGCO EQUIP (AB)

6 - 38403 BURNT LAKE TRAIL

RED DEER COUNTY, AB

CA T4S 2L4

Contact: Perry Doyle
pdoyle@strongco.com

T: (403)391-3520
F: (403)346-3487

#### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable. The condition of the oil is acceptable for the time in service.

Depot:VOLVO9652Unique No:5749445Signed:Kevin MarsonReport Date:26 Mar 2024



# **CONSTRUCTION EQUIPMENT**





### GRAPHS

