CONSTRUCTION EQUIPMENT 396629 CATERPILLAR MH3026 900404 - FRONT LEFT FINAL ORI

 Sample No:
 VCP393181

 Oil Type:
 CAT MTO M2C 134-D 10W30

 Job No:
 396629

SAMPLE INFORMATION

Manganese

Vanadium

Calcium

Zinc

Barium

Boron

Magnesium

Phosphorus

ppm

ppm

ppm

ppm

ppm

ppm

ppm

ppm

ADDITIVES

<1

3438

1071

3

92

11 1367

0

VOLVO

| Sample Number | - | VCP393181 | | |
|---------------|--------|--------------|------|--|
| Sample Date | | 26 Mar 2024 | | |
| Machine Hours | | 1350 | | |
| Oil Hours | | 1350 | | |
| Oil Changed | | Changed | | |
| Sample Status | | NORMAL | | |
| | | | | |
| OIL CONE | DITION | | | |
| Visc @ 40°C | cSt | 54.9 | | |
| | | | | |
| CONTAM | | | | |
| | - | | | |
| Water | % | NEG | | |
| Silicon | ppm | 1 3 | | |
| Sodium | ppm | 20 | | |
| Potassium | ppm | ■ <1 | | |
| | | | | |
| WEAR M | ETALS | | | |
| Iron | ppm | 60 | | |
| Copper | ppm | 58 | | |
| Lead | ppm | <1 | | |
| Tin | ppm | 0 | | |
| Aluminum | ppm | 1 | | |
| Chromium | ppm | 1 | | |
| Molybdenum | ppm | 0 | | |
| Nickel | ppm | 0 | | |
| Titanium | ppm | ■ <1 | | |
| Silver | ppm | 0 | | |
| | | | | |



STRONGCO EQUIPMENT-EDMONTON

25616 117 Ave NW Acheson, AB CA T7X 6C2 Contact: Jonathan Morton jmorton@strongco.com T: (780)464-1909 F: (780)464-0434

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.


| Depot: | VOLVO3908 | | |
|--------------|--------------|--|--|
| Unique No: | 5759267 | | |
| Signed: | Kevin Marson | | |
| Report Date: | 03 Apr 2024 | | |

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO



Report Id: VOLVO3908 [WCAMIS] 02626135 (Generated: 04/03/2024 09:08:26) Rev: 1

Contact/Location: Jonathan Morton - VOLVO3908