



# CONSTRUCTION EQUIPMENT

LAFARGE CANADA INC 402074 VOLVO L260H 1324 - TRANSMISSION (AUTO)



**Sample No:** VCP393864  
**Oil Type:** VOLVO AT 102  
**Job No:** 402074



## SAMPLE INFORMATION

Sample Number	VCP393864	---	---	---
Sample Date	23 May 2024	---	---	---
Machine Hours	2650	---	---	---
Oil Hours	500	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---

### STRONGCO EQUIPMENT INC.

1640 ENTERPRISE ROAD  
MISSISSAUGA, ON  
CA L4W 4L4

Contact: Janice Cripps  
jcripps@strongco.com  
T: (905)565-3876  
F: (905)670-2338



## OIL CONDITION

Visc @ 40°C	cSt	█ 27.6	---	---	---
-------------	-----	--------	-----	-----	-----



## CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 10	---	---	---
Sodium	ppm	█ 5	---	---	---
Potassium	ppm	█ 2	---	---	---



## WEAR METALS

Iron	ppm	█ 94	---	---	---
Copper	ppm	█ 11	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ 3	---	---	---
Chromium	ppm	█ <1	---	---	---
Molybdenum	ppm	█ 0	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	█ 0	---	---	---
Manganese	ppm	█ 5	---	---	---
Vanadium	ppm	0	---	---	---



## ADDITIVES

Calcium	ppm	79	---	---	---
Magnesium	ppm	█ 2	---	---	---
Zinc	ppm	█ 24	---	---	---
Phosphorus	ppm	█ 189	---	---	---
Barium	ppm	█ 4	---	---	---
Boron	ppm	█ 61	---	---	---

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

**Depot:** SHEMIS  
**Unique No:** 5787706  
**Signed:** Wes Davis  
**Report Date:** 30 May 2024



# CONSTRUCTION EQUIPMENT



## GRAPHS

