

CONSTRUCTION EQUIPMENT

HORST EXCAVATING VOLVO EC46OCL 110503 - COOLANT

Sample No: VCP148655

Oil Type: VOLVO COOLANT VCS (YELLOW)

Job No: HORST EXCAVATING

SAMPLE IN	IFORMATION				
Sample Number		VCP148655			
Sample Date		18 Dec 2015			
Machine Hours		3899			
Sample Status		NORMAL			
COOLANT CONDITION					
рН	Scale 0-14	7.60			
Reserve Alkalinity	Scale 0-20				
Nitrites	ppm	0			
Percentage Glycol	%	49			
Freezing Point	°C	-27			
CONTAMIN	IATION				
Coolant Appearance		normal			
Coolant Color		Orange			



HIGHWAY EQUIPMENT AND SUPPLY CO
200 BURKHOLDER DR.
EPHRATA, PA
US 17522
Contact: CHAD HERRON
chad@hwyequip.com
T: (717)859-3132
F: (717)859-2698

Diagnosis

The fluid is suitable for further service. There is no indication of any contamination in the component. The carboxylate level of this fluid is acceptable. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot:INSEPHUnique No:7256130Signed:Doug BogartReport Date:07 Jan 2016



CONSTRUCTION EQUIPMENT





GRAPHS

