

## **CONSTRUCTION EQUIPMENT** VOLVO EC460CL 110437 - LEFT SWING DRIVE



 Sample No:
 VCP205369

 Oil Type:
 SAE 85W140

#### Job No:

Phosphorus

Barium

Boron

ppm

ppm

ppm

	INFORMATION			
Sample Number		VCP205369	 	
Sample Date		28 Mar 2017	 	
Machine Hours		5004	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
OIL CON	DITION			
Visc @ 40°C	cSt	328.6	 	
	IINATION			
	%	NEG	<u>.</u>	
Water			 	
Silicon Sodium	ppm	8	 	
Potassium	ppm	■4	 	
Potassium	ppm	0	 	
VOLVO				
VEAR M	IETALS			
Iron	ppm	247	 	
Copper	ppm	8	 	
Lead	ppm	4	 	
Tin	ppm	<1	 	
Aluminum	ppm	<1	 	
Chromium	ppm	3	 	
Molybdenum	ppm	0	 	
Nickel	ppm	0	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm	3	 	
Vanadium	ppm	<1	 	
ADDITIV	ES			
Calcium	ppm	22	 	
Magnesium	ppm	3	 	
Zinc	ppm	28	 	



#### MCCLUNG-LOGAN EQUIPMENT CO - RICHMOND

1345 MOUNTAIN ROAD GLEN ALLEN, VA US 23060 Contact: KYLE RATLIFFE KRATLIFFE@MCCLUNG-LOGAN.COM T: F: (804)266-1611

### Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the component. The condition of the oil is acceptable for the time in service.

Depot:	VOLVO8882
Unique No:	7746540
Signed:	Doug Bogart
Report Date:	05 Apr 2017

896


0
116

# **CONSTRUCTION EQUIPMENT**



GRAPHS

VOLVO



Report Id: VOLVO8882 [WUSCAR] 04193120 (Generated: 03/05/2024 12:02:58) Rev: 1

Contact/Location: KYLE RATLIFFE - VOLVO8882